

0 1500 3000' 4500'



## FORMER MAR COM SITE (SOUTH) PORTLAND, OREGON

Report  
**REMEDIAL INVESTIGATION AND SOURCE  
CONTROL EVALUATION**

Drawing  
**SITE LOCATION MAP**

Date April 18, 2010

Scale AS SHOWN

Fig. No.

File Name 108.00242.00001-1

Project No. 108.00242.00001

1





NOTES  
AERIAL PHOTOGRAPH FROM PORTLAND MAPS.COM.

LEGEND  
----- PROPERTY BOUNDARY

FORMER MAR COM SITE (SOUTH)  
PORTLAND, OREGON

Report  
REMEDIAL INVESTIGATION AND SOURCE  
CONTROL EVALUATION

Drawing  
SITE PLAN

Date	April 15, 2010	Scale	AS SHOWN	Fig. No.	2
File Name	108.00242.00001-3	Project No.	108.00242.00001		

0 80 160 240'





















NOTES  
AERIAL PHOTOGRAPH FROM PORTLAND MAPS.COM.

#### LEGEND

- PROPERTY BOUNDARY
-  REMOVED BUILDING
-  EXISTING MONITORING WELL (PARAMETRIX 2001)
-  SURFACE SAMPLE (SLR 2007)
-  EXISTING MONITORING WELL (SLR 2006-2007)
-  TEST PIT LOCATION (SLR 2006)
-  GRIT/SLAG SURFACE SAMPLES (SLR 2006)
-  SLAG AND GRIT SURFACE SAMPLING (PARAMETRIX JANUARY 2000)
-  BORINGS (PARAMETRIX JANUARY 2000 AND MARCH 2000)
-  TEST PIT (PARAMETRIX MARCH 2000)
-  TEST PIT (RIEDEL APRIL 1993)
-  FORMER MONITORING WELL (RIEDEL MARCH 1993)
-  SUPPLEMENTAL ASSESSMENT (GEOENGINEERS APRIL 2004)
-  TEST PIT OR BORING LOCATION EXCAVATED
-  CONFIRMATION SAMPLES (SLR OCTOBER/NOVEMBER 2008)

### FORMER MAR COM SITE (SOUTH) PORTLAND, OREGON

Report  
**REMEDIAL INVESTIGATION AND SOURCE  
CONTROL EVALUATION**

Drawing  
**SAMPLING LOCATIONS**

Date	April 15, 2010	Scale	AS SHOWN	Fig. No.	4
File Name	108.00242.00001-3	Project No.	108.00242.00001		



0 80 160 240'





0 80 160 240'

NOTES  
AERIAL PHOTOGRAPH FROM PORTLAND MAPS.COM.

LEGEND

- PROPERTY BOUNDARY
- REMOVED BUILDING
- CATCH BASINS
- STORMWATER CONVEYANCE (APPROX. 2FT BGS)
- OUTFALL
- OFF-SITE OUTFALL

FORMER MAR COM SITE (SOUTH)  
PORTLAND, OREGON

Report  
REMEDIAL INVESTIGATION AND SOURCE  
CONTROL EVALUATION

Drawing  
STORMWATER CATCH BASINS  
/STORMWATER OUTFALLS

Date April 15, 2010

Scale AS SHOWN

Fig. No.

File Name 108.00242.00001-3

Project No. 108.00242.00001

5










NOTES  
AERIAL PHOTOGRAPH FROM PORTLAND MAPS.COM.

LEGEND

- PROPERTY BOUNDARY
-  REMOVED BUILDING
-  EXISTING MONITORING WELL (PARAMETRIX 2001)
-  EXISTING MONITORING WELL (SLR 2006-2007)
- 14.54 RELATIVE GROUNDWATER ELEVATION CONTOUR
- ESTIMATED GROUNDWATER CONTOUR

\* MW-1 NOT USED FOR THE CONSTRUCTION OF THE GROUNDWATER GRADIENT

FORMER MAR COM SITE (SOUTH)  
PORTLAND, OREGON

Report  
REMEDIAL INVESTIGATION AND SOURCE  
CONTROL EVALUATION

Drawing  
GROUNDWATER GRADIENT MAP 2/21/2008

Date	April 15, 2010	Scale	AS SHOWN	Fig. No.	10
File Name	108.00242.00001-3	Project No.	108.00242.00001		



0 80 160 240'





NOTES  
AERIAL PHOTOGRAPH FROM PORTLAND MAPS.COM.

LEGEND

- PROPERTY BOUNDARY
- REMOVED BUILDING
- APPROXIMATE EXTENT OF GRIT REMOVAL

FORMER MAR COM SITE (SOUTH)  
PORTLAND, OREGON

Report  
REMEDIAL INVESTIGATION AND SOURCE  
CONTROL EVALUATION

Drawing  
APPROXIMATE EXTENT OF GRIT REMOVAL

Date	April 15, 2010	Scale	AS SHOWN	Fig. No.	13
File Name	108.00242.00001-3	Project No.	108.00242.00001		



0 80 160 240'